

Park Component	Condition			Capacity			Notes
	Poor	Fair	Good	Under	At/Over		
Vegetation (Trees, shrubs, turf)		X			X		Turf dry
Play Areas		X			X		Large open green space
Sports Fields	X				X		1 soccer field, 1 backstop in poor condition
Sports Courts		X			X		2 basketball courts
Walks/Trails	X				X		Dirt track
Play Equipment			X		X		2 play structures, tires and other playground equipment
Structures							None at this location
Picnic Facilities							None at this location
Drinking Water							None at this location
Restrooms							None at this location
Parking		X			X		Paved parking lot out front
Lighting							None at this location
Benches							None at this location
Signage		X			X		School sign

Source: JEO Consulting Group, Inc., 2013

Table: 49: Sandoz Elementary Park, Lexington

## *“The Lex-Plan 2013”*